1. Initiator	LAST NAME FIRST	2. Type of Review	3. RID Number
Name	Harkins, Michael	General Document Review	00200-307
Organization	USA 5224		0020000
Phone		PDR, CDR, ABR , PPR (circle)	
	1-7826	☐ Other	_
Fax	1-7886		
5- Dee Neacher	(Dec News		
5a. Doc. Number	84K00200 6. Doc. Name System	n Level Specification (SLS)	
5a. Doc. Revision	Pre-Release 1		
6. Name of RID Team SI S. D.ID. Davious Toom			
6. Name of RID Team SLS RID Review Team			
7. Problem			
2.2.11.2.16 states:			
All Orbiter/GSE signal paths shall be capable of being monitored without opening racks or disrupting the signal path.			
8. Recommendation			
2.2.11.2.16 should state:			
All Orbiter/GSE signal paths shall be capable of being monitored without removing panels or disrupting the signal path.			
Hardcopy of Redlines/Comments Attached			
9. Impact if recommendation not implemented			
Some racks and VME chassis will have EMI doors.			
Some racks and vivil chassis will have livil doors.			
		Initiator - Signature	Submission Date
10. Team Recomm	endation	11. Action Required	
Accer	oted	Update Document	
☐ Rejec	cted	☐ Study	
☐ Study	V	Other (specify)	
_	drawn		
☐ Defe Comm	rred to CLCS CCB Screening Panel	Comments	
Com	nents	Comments	
RID Team Manager	- Signature		
12. Final RID Clo	sure Action	13. Additional Comments/Notes	
RII	O to be incorporated in next revision	A. Maditional Community (1905)	
☐ RID to be incorporated in other (specify)			
Last to be incorporated in other (specify)			
RID Team Manager	- Signature		